

Appendix I: Case study Mercon Kloos: Value assessment matrix





Appendix II: Case study NDSM Wharf: General characteristics in relation to adaptive reuse


"SCHEEPSBOUWLOODS"

Preserved characterisitcs










Translation to function



Visibility of structure and little obstructions





Unobstructed, large interior areas


Daylight through several skylights


"LASLOODS"

Preserved characterisitcs










Translation to function



Visibility of structure and little obstructions



Unobstructed, large interior areas

Daylight through several skylights

The general characteristics of maritime heritage

in relation to the adaptive reuse process