












LEGEND



- 0. PAVILION
- A. CAPUCIJNENSTRAAT WING
- B. APOSTELENGANG
- C. MISERICORDESTRAAT
- D. MISERICORDEPLEIN
- E. APOSTELENPAVE
- 1. SISTERS' CHAPEL
- 2. LAYMEN'S CHAPEL
- 3. LAUNDRY AND IRONING WING 1
- 4. LAUNDRY AND IRONING WING 2
- 5. ADDITION 2017








CROSS SECTION NEW WING - 1:50






DETAIL 01 - ROOF/WINDOW - 1:5

LEGEND


1. NATURAL STONE EAVES
2. FLEMISH MASONRY BAND
3. INSULATION - POLYISOCYANURATE (PIR) 100 MM
4. RAINWATER DRAINAGE
5. TIMBER CHOCK
6. CONCRETE LINTEL
7. PINEWOOD BOARDS WITH COLORLESS VARNISH
8. HOLLOW CORE SLAB
9. PRESSURE-PROOF INSULATION
10. BITUMEN ROOFING
11. GRAVEL
12. WATERPROOF FOIL
13. MOUNTING FRAME
14. WINDOW FRAME
15. INWARD ROTATING WINDOW
16. INSULATED GLASS PANELS
17. OPEN JOINT
18. PREFAB CONCRETE WALL
19. PREFAB CONCRETE BEAM WITH BRICK FINISH
20. SCREED FLOOR
21. LAMINATE FLOOR
22. WOOD FINISHING
23. BATTENS



DETAIL 02 - STRUCTURAL BEAM/WINDOW - 1:5

LEGEND


- I. NATURAL STONE EAVES
2. FLEMISH MASONRY BAND
3. INSULATION - POLYISOCYANURATE (PIR) 100 MM
4. RAINWATER DRAINAGE
5. TIMBER CHOCK
6. CONCRETE LINTEL
7. PINEWOOD BOARDS WITH COLORLESS VARNISH
8. HOLLOW CORE SLAB
9. PRESSURE-PROOF INSULATION
10. BITUMEN ROOFING
- II. GRAVEL
12. WATERPROOF FOIL
13. MOUNTING FRAME
14. WINDOW FRAME
15. INWARD ROTATING WINDOW
16. INSULATED GLASS PANELS
17. OPEN JOINT
18. PREFAB CONCRETE WALL
19. PREFAB CONCRETE BEAM WITH BRICK FINISH
20. SCREED FLOOR
21. LAMINATE FLOOR
22. WOOD FINISHING
23. BATTENS




CROSS SECTION LAUNDRY AND IRONING WING - 1:50




DETAIL 03



FRAGMENT I - FRAME - CROSS SECTION 1:20




DETAIL 03 - EAVES FRAME - 1:5



DETAIL 04 - FLOOR CONNECTION FRAME - 1:5





LEGEND

- A. EAVES
- B. COATED AND ACETYLATED PINEWOOD BOARDS (IN DUTCH: "GRENNENHOUT"), BY ACCOYA
- C. BATTENS
- D. TIMBER FRAME ELEMENT
- E. INSULATED GLASS PANEL
- F. STRUCTURE FRAME
- G. WINDOW FRAME
- H. INSULATION
- I. PINEWOOD BOARDS WITH COLORLESS VARNISH
- J. GUTTER
- K. BITUMEN ROOFING
- L. LAMINATE FLOOR
- M. FIRE-RESISTANT PANELS; 90 MIN
- N. ACOUSTIC PLASTER
- O. FACING WALL




DETAIL 05 - BOTTOM CONNECTION FRAME - 1:5






FRAGMENT 2 - LAMELLA - CROSS SECTION I:20




LEGEND


- A. FACING WALL
- B. PINWOOD BOARDS WITH COLORLESS VARNISH
- C. STEEL LINTEL
- D. MOUNTING FRAME
- E. WINDOW FRAME
- F. INSULATED GLASS PANEL
- G. WELDED BOLT
- H. LAMINATED TIMBER LAMELLA
- I. LAMINATE FLOOR
- J. MORTAR
- K. STEEL CONNECTION
- L. WINDOW SILL




ELEVATIONAL VIEW - 1:50




HORIZONTAL SECTION - 1:50




VERTICAL SECTION - 1:50




DETAIL 07 - GUTTER AND ISOLATION ROOF - 1:5



DETAIL 08 - ADDITIONAL WINDOW - 1:2




DETAIL 09 - ADDITIONAL WINDOW - 1:2




DETAIL 10 - ADDITIONAL WINDOW - 1:2

LEGEND


1. NEW GUTTER
2. NEW ROOF SLATES
3. WATERPROOF BREATHABLE FOIL
4. INSULATION
5. VAPOR OPEN FOIL
6. PLYWOOD PANELS
7. STEEL PROFILE
8. ALUMINUM FRAME
9. 10 MM LAMINATED GLASS




FIRST PAINTLAYER








SECOND PAINTLAYER



REVEALING FIRST PAINTLAYER



IMPRESSION TRAPEGGIO TECHNIQUE



DAMAGES

- LEGEND
- █ MOISTURE DAMAGE
 - █ EXFOLIATION
 - █ CRACKS
 - █ FLOOR