Erratum to “Effects of misalignment on the undrained HV capacity of suction anchors in clay” (Ocean Engineering (2017) 133 (89–106) (S0029801817300483) (10.1016/j.oceaneng.2017.01.033))

Saviano, Alessio; Pisanò, Federico

DOI

[10.1016/j.oceaneng.2017.03.044](https://doi.org/10.1016/j.oceaneng.2017.03.044)

Publication date

2017

Document Version

Final published version

Published in

Ocean Engineering

Citation (APA)

Saviano, A., & Pisanò, F. (2017). Erratum to “Effects of misalignment on the undrained HV capacity of suction anchors in clay” (Ocean Engineering (2017) 133 (89–106) (S0029801817300483) (10.1016/j.oceaneng.2017.01.033)). *Ocean Engineering*, 136, 330.
<https://doi.org/10.1016/j.oceaneng.2017.03.044>

Important note

To cite this publication, please use the final published version (if applicable).
Please check the document version above.

Copyright

Other than for strictly personal use, it is not permitted to download, forward or distribute the text or part of it, without the consent of the author(s) and/or copyright holder(s), unless the work is under an open content license such as Creative Commons.

Takedown policy

Please contact us and provide details if you believe this document breaches copyrights.
We will remove access to the work immediately and investigate your claim.

The publisher regrets to notify an error in the abovementioned publication. Specifically, a wrong version of Eq. (3) was provided in the text. The amended equation is given hereafter:

$$\left(\frac{H}{H_{ult}}\right)^a + \left(\frac{V}{V_{ult}}\right)^b = 1, \quad a = 0.5 + \frac{L}{D} \quad b = 4.5 - \frac{L}{3D}$$

The publisher would like to apologise for any inconvenience caused.