

Corrigendum to “Dynamic response of an offshore structure interacting with an ice floe failing in crushing” (Marine Structures (2019) 65 (271–290), (S0951833918303496), (10.1016/j.marstruc.2019.01.012))

Hendrikse, Hayo; Nord, Torodd S.

DOI

[10.1016/j.marstruc.2019.102706](https://doi.org/10.1016/j.marstruc.2019.102706)

Publication date

2020

Document Version

Accepted author manuscript

Published in

Marine Structures

Citation (APA)

Hendrikse, H., & Nord, T. S. (2020). Corrigendum to “Dynamic response of an offshore structure interacting with an ice floe failing in crushing” (Marine Structures (2019) 65 (271–290), (S0951833918303496), (10.1016/j.marstruc.2019.01.012)). *Marine Structures*, 70, Article 102706.
<https://doi.org/10.1016/j.marstruc.2019.102706>

Important note

To cite this publication, please use the final published version (if applicable).
Please check the document version above.

Copyright

Other than for strictly personal use, it is not permitted to download, forward or distribute the text or part of it, without the consent of the author(s) and/or copyright holder(s), unless the work is under an open content license such as Creative Commons.

Takedown policy

Please contact us and provide details if you believe this document breaches copyrights.
We will remove access to the work immediately and investigate your claim.

Corrigendum

Corrigendum to Dynamic response of an offshore structure interacting with an ice floe failing in crushing Marine Structures 65 (2019) 271-290

Hayo Hendrikse^{a,b,*}, Torodd S. Nord^b

^a Department of Hydraulic Engineering, Delft University of Technology, Stevinweg 1, 2628 CN, Delft, the Netherlands

^b Sustainable Arctic Marine and Coastal Technology, Norwegian University of Science and Technology, Høgskoleringen 7A, 7491, Trondheim, Norway.

The authors regret their mistake in the definition of the model parameters in Eq. (8) on page 277. The correct equation for the parameter C_2 is:

$$C_2 = \frac{F_t^3}{N^3 v_t}$$

The authors would like to apologise for any inconvenience caused.

DOI of original article: <https://doi.org/10.1016/j.marstruc.2019.01.012>

* Corresponding author. Department of Hydraulic Engineering, Delft University of Technology, Stevinweg 1, 2628 CN, Delft, the Netherlands.

E-mail address: h.hendrikse@tudelft.nl (H. Hendrikse).