



**1 Finding the design solution space:** Establish the boundaries for redesign by identifying where material can be added and where it cannot. Refer to example card 'Defining the solution space' for more detailed explanations and examples.



**2 Exploring print orientations:** Experiment with different print orientations and solutions to satisfy part usage requirements. Refer to example cards 'Smoothness', 'Dimensional accuracy' and 'Strength' for detailed explanations and examples per part requirement.



**3 Run slicer:** Run the slicer in on the oriented models to gain further learnings on printability, taking into account all insights on redesign possibilities to see if they are solvable.

