


POPSTAGE SANTOS



Content

Situation

Cultural values

Program

Masterplan

Concept


Context

Vide

Popstage

Which interventions are needed to let a historical coffee warehouse interact again in the context without loss of identity?

Situation
coffee warehouse



Situation

Rotterdam Zuid



Situation

Katendrecht



Situation

Katendrecht



1905



1975



2004

Situation

Santos



Situation
Afrikaanderwijk




Situation

connections




Situation

Jumbo



Situation

car garages



Situation

The View- European China Center Rotterdam



Original program process




Coffee production area around Santos



Last samples are taking before export



Stamping bags for export




Interior of a Santos cleaning and grading warehouse where coffee is prepared for export

Original program process



Trade route between Santos and Rotterdam



Unloading the ships




Vertical circulation




Unloading and loading in a coffee store

Original program process



Section of the transport in the warehouse




Santos in 1920


Cultural values

starting points




Area



Context



Building




Low value
Medium value
High value

Cultural values area



Cultural values area



Cultural values area





Cultural values

area






Cultural values context




Cultural values

context



Cultural values building



Cultural values building



Floor load:

300 kg/m²

1.200 kg/m²

1.500 kg/m²


1.500 kg/m²

2.200 kg/m²








2.200 kg/m²

4.000 kg/m²



3.000 kg/m²




Cultural values building




Cultural values building




Basement



Ground floor



1st- 4rd Floors



5th Floors

Storage space


Vertical circulation

Office

Toilets




Cultural values

conclusion



Cultural values

conclusion





Gemeente Rotterdam wil nieuw poppodium

'H^et podium moet een plaats zijn waar lokale, nationale en internationale acts hun volgende stap kunnen zetten als ze de bestaande Rotterdamse podia zijn ontgroeid', zegt verantwoordelijk cultuurwethouder Adriaan Visser. De Maasstad heeft sinds 2010 geen poppodium meer.

Program

inhabitants Katendrecht & Afrikaanderwijk



21 %
children



10 %
students



57 %
adults



12 %
elderly

4.755
inhabitants



18 %
children



16 %
students



53 %
adults



13 %
elderly

8.075
inhabitants

Masterplan

current situation



Masterplan

current situation




Masterplan
demolition plan



Masterplan

new buildings



Masterplan

program



Masterplan

square



Masterplan
routing




Masterplan

greenery





Concept

existing situation





Concept

extrovert





Concept

extrovert






Concept

connection with the square




Concept

relation with the water



Interaction


cultural routing



- 1. Santos
- 2. LT dance
- 3. Theater walhalla


- 4. LantarenVenster
- 5. Nieuw Luxor Theater
- 6. Drijvend Paviljoen

Strategy
construction





Strategy


construction




Strategy
construction








Strategy
program




Strategy


program



Strategy program






Strategy extension





Strategy

extension




Strategy


extension



Strategy extension




Strategy extension






Strategy

routing





Facade

daylight






Facade

daylight





Facade


daylight




Facade

daylight






Ground floor program




Ground floor routing






Strategy

program




Strategy program




Strategy

program




Floorplans




1st floor

2nd floor




Floor system

existing floor





Floor system

double floor




Floor system

double floor



Climate system

ventilation




winter


summer

Climate system


cooling & heating



Floorplans



3rd floor










4th floor






Construction concept




Construction


exploded view




Section cross section




Floorplans



5th floor




6th floor








Section
popstage



Section soundproofing




Section




longitudinal section








Section
fragment



Section
details skybar





Section
details skybar





Section



intervention ground floor



Section
insulation








Section
insulation



Section

intervention ground floor



Materials finishing

