


P5 DRAWINGS


19 - 04 - 2018



SANTOS - ALL DRAWINGS

ROTTERDAM

Daan Deen - 4410696



01 NORTH FACADE


< existing | new >





02 SOUTH FACADE

< existing | new >







03 EAST FACADE

< existing | new >






fire escape dropped down



04 WEST FACADE

< existing | new >






fire escape dropped down

05 GROUND FLOOR

- 001** entrance public
- 002** grand cafe
- 003** bar
- 004** main staircase & elevator office
- 005** entrance office

- 006** kitchen
- 007** toilets
- 008** entrance disabled person
- 009** main staircase

- 101** storage
- 102** cleaning cupboard / storage
- 103** employee area
- 104** elevator public




06 FIRST FLOOR

- 001** entrance public
- 002** main staircase
- 003** main staircase & elevator office
- 004** toilets office meeting rooms
- 005** employee breakroom

- 006** toilets

- 101** storage
- 102** meeting room
- 103** employee area
- 104** elevator public



07 TYPICAL OFFICE FLOOR

- 001** small office 40m²
- 002** medium office 80m²
- 003** large office 120m²
- 004** main staircase & elevator office
- 005** breakroom

- 006** toilets
- 007** small meeting room

- 101** storage
- 102** cleaning cupboard / storage



08 ROOF GARDEN

- 001** main staircase
- 002** entrance to the roof

